

Subject: Sector 7 Safety Inspection Report

From: Diane Morgan <morgan@aps.anl.gov>

Date: Fri, 26 Jan 2007 11:38:42 -0600

To: Eric Dufresne <dufresne@aps.anl.gov>

CC: Gabrielle Long <gglong@aps.anl.gov>, Mark Beno <beno@aps.anl.gov>, George Srajer <srajerg@aps.anl.gov>, Jin Wang <>wangj@aps.anl.gov>, Dohn Arms <dohnarms@anl.gov>, "Donald A. Walko" <d-walko@anl.gov>, Paul Rossi <prossi@aps.anl.gov>, flcoord@aps.anl.gov

Division: XSD Location: Sector 7

Date of Inspection: 01/25/07

Inspected by: George Srajer, Eric Dufresne, Don Walko, Dohn Arms, Harrold Gibson,
and Paul Rossi


The following items were identified during the inspection.

** Please send a reply e-mail indicating the corrective actions taken.**

1. 432/D020: Emergency contact information needs to be updated (floor coordinator).



2. 432/D030: Emergency contact information needs to be updated (floor coordinator).



3. 7-BM-A: No issues, good job.

4. 7-BM-B: No issues, good job.

5. 7-ID-A: Oxygen monitoring no longer required. Remove as legacy equipment (floor coordinator).



6. 7-ID-B: Mixed utilities in cable tray.



7. 7-ID-B: Temporary extension cords used as permanent power.



8. 7-ID-B: Mark utilities with content and direction of flow.




9. 7-ID-C: Electrical grounding wire should be bare or green.
-



10. 7-ID-C: Mark utilities with content and direction of flow.
-



11. 7-ID-D: Laser operating permit expired.



Paul